DECISIONS TAKEN IN THE BOARD MEETING HELD ON 24.5.1978.

While reviewing the report on "water supply " containing the short term measures recommended therein to improve the water supply position, the following decisions were inter-alia taken by the Board in its meeting held on 24.5.1978 in Chairman's office, for immediate compliance:-

OVER_HEAD TANK IN SECTOR G_6/2.

J261/620/78

It was brought to the notice of the Board for the first time that an over-head tank of 1 M.G.D. capacity constructed in G-6/2 was lying un-utilized due to certain short-comings. The Board took a serious view of the situation and directed that the file dealing with the construction of this over-head tank alongwith all relevant information i.e. how, when and by whom this tank was constructed and why it had not been commissioned to-date should be submitted to the Chairman within a day or two.

Action by: D.G.W.-I. 2. Director W & S.

2. TUBE_WELLS NO.10 AND 11.

It was reported that there was no water in these tube-wells with the result that the pumping equipment installed on these tube-wells was lying idle. The Board desired to know the reasons why these tube-wells were sunk in the first place when there was no under-ground water and consequently the pumps were not likely to yield any water. It was decided that relevant files dealing with these tube-wells should be put up alongwith the names of the persons responsible for the planning and execution of these tubewells.

Action by: D.G.W.-I
2. Director W & S.

3. TUBE_WELLS AT SECTOR I.10.

3263/620/78

The file dealing with the choked tube-well in Sector I-10 alongwith the inquiry report and the ultimate result of the inquiry should be put up to the Board immediately.

Action by: Director W & S.

FIVE OVERHEAD TANKS IN SECTOR F-6, G-7 AND H-9.

Director W & S explained that two of the five over-head tanks in Sector F-6 had been completed, two in Sector G-7 were nearing completion and one in Sector H-9 was still under construction. The Chairman observed with

1

concern that the construction of these over-head tanks was under-taken as far back as 1973 and it was a matter of grave concern that these had not yet been completed even after the expiry of five years. It was decided that a detailed note indicating the reasons for this in-ordinate delay in the construction of these tanks and the names of persons responsible for their execution should be submitted to the Board expeditiously.

Action by: 1. DGW-I.
2. Director W&S.

RL_I PIPE LINE.

3265/620/78

It was decided that an inquiry should be conducted by Director Designs to determine the reasons for premature deterioration of the said pipe line when normally the life time of such pipe line ranges between 25-30 years. The names of the persons responsible for the planning and execution of the Project should also be indicated in the report. The report should be submitted to the Board within 10 days.

Action by: Director Designs.

WATER PUMPS INSTALLED IN 1976.

3266/620/78

With reference to the proposal, made in the report on water supply, for the replacement of water pumps installed in the year 1976, the Board desired to know the reasons why these pumps were required to be replaced after such a short period when similar pumps installed years before the installation of these pumps were still operating satisfactorily. Recommendations for replacement of these pumps made in the report on "water supply" should be substantiated with facts and figures.

Action by: Director W & S.

TRIMMING OF TREES.

3267/620/78.

Directorate, CDA do not trim the trees along the property head electric lines feeding the water reservoir and consequently the wires get tripped when-ever there is rain or storm resulting electric failures. In order to overcome this problem, it was decided that all such trees which affect the over-head electric lines feeding the water reservoirs should be cut by the Hort: Directorate immediately.

Action by: Director Hort: