

Subject: Chairmen's orders passed during the  
Special Board Meeting held on 4th  
August, 1977.

During the Special Board meeting, besides the decisions taken and to be recorded on the relevant files, the following orders were passed by the Chairman for immediate and strict compliance by all concerned :-

3230/614/77.

1. ACCUMULATION OF RAIN WATER AND DRAINING THEREOF.

It was observed that during rains, water accumulates at a number of road crossings. Accumulated rain water is also reported to have entered the basement of the Secretariat Buildings. DGW was asked to investigate if this was due to any drainage failure and if so, he should fix the responsibility. He may also get the defects/depressions in roads where water accumulates rectified. Report be submitted by 20.8.77. (Action: DGW)

2. PROVISION OF EXTRA GRATINGS IN FRONT OF  
FACADE BLOCK-II.

3231/614/77

For over three months the Director Maintenance is being asked to provide extra gratings on the drainage in front of Facade Block-II. He was also asked to carry out the construction of the collapsed boundary wall of the CDA Sectt: (Facade Block-II). Nothing has been done so far in this respect. DGW would please take necessary action in the matter and would also furnish by 20.8.77 the reasons for not carrying out the job.

(Action: DGW  
D/Maintenance.)

3. WHOLESALE VEGETABLE MARKET.

3232/614/77.

It was reported that the wholesale vegetable market was being converted into a retail market. It was further complained that some of the allottees of the market had set up 'tharhas' and had sub-let the same. DMA was asked to inquire into the matter and eject the defaulters. Director Municipal Administration was requested to call the allottees to ensure that they undertake whole sale business strictly according to the terms and conditions of allotment.

(Action: DMA)

Contd..2.

(6)

4.

3233/614/77.

CONTROL OVER THE INCREASE IN THE NUMBER OF  
KHOKHAWALAS.

The number of 'Khokhawalas', which, according to initial census, was recorded to be about 287, is stated to have swollen up to about 1200. This is inspite of the fact that some of the 'Khokhawalas' have been shifted to regular shops. DMA was asked to prepare a detailed list along with his report as to how the problem should be tackled.

(Action: DMA)

5.

3234/614/77

IMPOSITION OF TRADE RESTRICTIONS IN THE  
CAPITAL AREA.

Trade restrictions to be imposed in the Capital area if no provision to that effect has been made so far.

(Action: DMA)

6.

3235/614/77.

ACCUMULATION OF WATER IN  
SUPER MARKET F.6

The problem of accumulation of water in Block 'D' of Super Market F-6 should be looked into immediately and remedial measures taken. Piled up construction material should also be lifted from different localities.

(Action: D/Maintenance  
D.M.A.)

7.

3236/614/77.

CONSTRUCTION OF CHINESE EMBASSY.

Work on Chinese Embassy should be completed by 15.8.77 and DGW should visit the site daily to ensure compliance.

(Action: DGW)

8.

3237/614/77.

POSITIONING OF MAINTENANCE SQUAD ROUND THE CLOCK.

One squad with the necessary staff should be available at-least in one Enquiry Office round the clock.

(Action: D/Maintenance)

9.

3238/614/77.

CONSTRUCTION OF ROAD LEADING TO DAMN-E-KOH.

Progress on the roads leading to Damn-e-Koh was reviewed. The Chairman observed that it was un-satisfactory and it should be expedited.

(Action: DGW  
D/Inspection)



(7)

10.

CONSTRUCTION OF MARGALLA ROAD

3239/614/77.

The work on the Margalla Road was also not found to be progressing satisfactorily. Director Inspection explained that this was due to the fault of contractor. He was directed to see that if the contractor did not carry out the work properly, the contract should be terminated.

(Action: D/Inspection)

11.

INSTALLATION OF PRE-FABRICATED HUTS

3240/614/77

The work of dis-mantling of the pre-fabricated huts and their installation at the Damn-e-Koh and Rawal Dam sites was discussed. It was decided that it will be got done by DGW under the guidance of Member (Tech).

(Action: DGW)