THE ZOTH FEBRUARY 1953 AT 10 OR OM THE 20TH FE 32 UASY . 19 53 AT 10.00 AM

The meeting was presided over by Mr. S. A. P. Sandezi, chairman, cond the following were also present:

1. Hr. Nohammad Saced Oureahl, Member (Admn). 2. Mr. S. H. Reza. 3. Brig. Nohammad Anwar. Member (Tech) . . Ar. Ajaz A. Khan. Secretary. 5. Ir. N. Shafi Sewhani. Director General dorks. 6. Mr. Mohi-ud-Din Jameeli. Director Works. . Mr. A. G. Nomani. Director (W&S). S. Hr. Nohammad Aslam. Director "oads, . Mr. Abdul Khaliq Beg. Director Electrical/ Mechanical. D. Hr. Abdus Salam Khan Wazir. Director Maintenance. . Nr. 11, Habibullah Khan. Director Design & Pegearch. 2. Mr. N. Ashraf Hafeez. Director Horticulture. 3. Mr. Abdul Waheed. Director Furchases & Stores. Mr. Mustafa Kamal Pasha. Director Planning. 5. Nr. Anwar Said. Director Architecture.

6. Lt. Col. (Retd) Nubarak Ahmed Malik. Director Enforcement and Intelligence. Deputy Financial Adviser.

T. Fida Hussain. 8. Col. (Retd) Mehbub Alam Malik. Director Municipal Admin:

Director Audit & Accounts. 9. Fr. Zafar Ahmed.

Director Estate Management. O. Mr. Dinait Ali.

Mr. Nisar Ahmed. Statistical Officer. 2. Pr. Hohammad Mansha Yad.

Public Pelations Officer.

The agenda circulated vide Coordination Section's Pemo: . C14-657/SII-Coord/83, dated 2,2,1983 and even number dated 7,2,1983, was considered, and the following decisions were aken:

1. SUB-DIVISION OF RESIDEITIAL PLOTS IT ISLAMASAD.

546/657/83. 1(25) -Coord/83.

The summary was explained by the Director Planning on behalf of Director Estate lianagement who was attending one week's training course. After some discussion, it was felt that the summary and its recommendations in the present form are not acceptable. It was, however, desired that the case may be brought up if there are some additional arguments in support of the recommendations.

Action by: -1. Nirector Estate Panagement. 2. Director Planning.

Contd. P. 2.

(2): 2. NAMING OF A ROAD IT ISLAMABAD AFTED THE PAME OF RALA GHAZANFAD ALI KHAN, A CLOSE ASSOCIATE OF QUAID E -AZAM,

547/657/83. 12/BF Coord/73. The Secretary submitted the case indicating that a letter addressed to the Chairman, CDA has been received from the General Secretary, Raja Ghazanfar Ali Khan Memorial Society, Pind Dadan Khan, District Jhelum Luggesting that one of the Shahrahs of Islamabad may be named after Raja Ghazanfar Ali Khan. On enquiry from the Chairman, it was explained that the original scheme for naming of roads, sectors etc. in Islamabad, had been approved by the Cabinet, The Public Pelations Officer also explained that certain changes had been proposed by the CDA which were submitted to the Government for approval, and no decision has so far been received. After some discussion it was decided that a Committee consisting of Member (Admn), Secretary and Public Relations Officer should examine the whole issue with reference to the summary/recommendations of the Secretaries Committee and the Cabinet decisions. The case may thereafter be put up for consideration of the Board.

> Action by: -Public Relations Officer.

3. MONTHLY REVIEW SUMMARY.

548/657/83. 90/BF-Coord/80.

490/BF-Coord/80.

1. ALWAN-E-SADR COMPLEX

Separate staff should now be appointed for the maintenance of Aiwan-e-Sadr. The Director General Works was advised to expedite the progress the case with Member (Tech), F. A. (Member) and Chairman.

Action by: -

- 1. Director General Worsk. 2. Director Personnel.
- 3. Director Buildings.
 4. Deputy Financial Adviser.
 5. Deputy Director (0 & M).

2. ALWAN -E -S ADR COLONY

c) 10 F to 1 type houses.

The F to I type houses which have been completed may be used for housing the CDA staff (Maintenance staff of the Alwan-e-Sadr) temponarily.

Action by: -

- 1. Director General Works.
 2. Director Buildings.
 3. Director Maintenance.

 - 4. Director Horticulture.

BF -Coord/80,

3. CABINET/ESTABLISHMENT BLOCK

Un an enquiry from the Chairman, it was indicated that the work on shifting of electricity and telephone lines was being progressed by WAPDA and T & T Department, it was desired that the agencies concerned should be chased to have the work completed most expeditiously.

Action by: .

- 1. Director General Works. 2. Director Electrical. 3. Director Mechanical.

4. CONSTRUCTION OF FARLIAMENT BUILDING

It was desired that the progress on the Parliament Building should be accellerated.

Action bys-

1. Director General Works. 2. Director Buildings.

6. CONSTRUCTION OF GASMIA MASJID IN F-8/3

The Chairman observed that the CDA should not get involved with the Imam and construction work should be carried out according to the plans, The Director General Works indicated that the work cannot be done unless the mam in this case hand over the premises, The Deputy Commissioner, Islamabad was also reported to have informed that the Imam should not be disturbed as it was going to cause law & order situation. The Chairman advised the Director General Works to inform the Deputy Commissioner about the Fresident's decision and ask him to assist the CDA in pregressing the work according to President's directive,

Action by: -

- 1. Director General Works.
- 2. Director Works.
 3. Director Elligence. w
- 4. Coordination Section.

13. ADDITIONAL OFFICE BLOCK OF THE REAR OF FACADE BLOCK- 11

The Director General Works reported that the additional block behind the Facade Block was nearing completion. He proposed that it may be used for his offices. It was observed that this block would not be available for occupation by the offices of D.G.W.

BF-Coord/80.

70) -Coord/81.

3/8F-Ccord/80.

Contd 4. It was decided that Member (Admn) would look into the Utilisation/allocation of space in this block and the Director General Morks may explore to use the accommodation in the Parliament Building for his offices.

Action by:

Administrative Officer.

16. CONSTRUCTION OF FIRE SUB-STATION IN ADMN: SECTOR.

363/BF-Coord/80.

It was observed that the fire sub-station in the Admin Sector was too big and accommodation therein could be used for CD' offices till such time their plants and equipment for its full utilisation are available.

Action by: -

1. Director General Morks. 2. Administrative Officer.

22, PERAIRING OF COOLING TOWER AT PRASE-I SECRETARIT BUILDINGS

363/BF-Coord/80. The Chairman directed that the new chillars should be used in the Phase-I Secretariat Bldgs and the old one should be got repaired through some good/established firms.

Action by: -

- 1. Director General Yorks.
 2. Director Electrical.
- 3. Director Mechanical.

29. CONSTRUCTION OF 864 FLATS IN 1-8

The Director General Works was asked to fix a date of Chairman's visit to the flats in Sector 1-8 sometime next week.

Action by: -

1. Director General Yorks. 2. Director Yorks.

33. BOOMOCASTING MOUSE

569/BF-Coord/ .

23(1) -Coord/77.

It was pointed out that the airconditioning plant had been installed about two years ago and some defects in one of the three boilers have developed during this period as it remained idle. Those defects have been/are being attended to. It was further pointed out that although the building has been completed and is also in use but no maintenance funds are being provided. The Director General works

was directed to write to the Broadcasting authorities for provision of maintenance funds.

Action by: -

- 1. Director General Works.
- 2. Director Maintenance.
 3. Director Buildings.
 4. Deputy Financial Adviser.

35. CONSTRUCTION OF 2000 GOVER MIENT POUSES.

BF-Coord/76.

It was indicated that the progress of work on 2,000 Government houses was satisfactory but the availability of funds has been creating problems. It was decided that a letter should be sent to Secretary Works under the signatures of Chairman, COA for provision of funds. The Deputy Financial Adviser was asked to put up the draft quickly,

Action by: -

- 1. Director General Works. 2. Director Works. 3. Deputy Financial Adviser.

IV. DIRECTOR ATE OF POADS.

3/BF -Coord/80.

It was decided that the progress on roads may be reviewed by Member (Tech).

Action by: -

- 1. Director General Works.
- 2. Director Roads.

For the remaining items, it was decided that the progress should be brought up to date.

Action by: -

- 1. Director General Works.
- 2. Director Roads.

- 3. Director Works.
 4. Director (W & S).
 5. Director Electrical.
 6. Director Mechanical.